

POSTED at  
25/06/2026, 19:15:21

## STEWARDS' DECISION

**From:** The Stewards

**To:** Kessel Racing

The Stewards, having received a report from the Technical Delegate, summoned and heard from the competitor's representative, have considered the following matter and determine the following:

**No. / Driver:** 74 -

**Competitor:** Kessel Racing

**Time:** 17:10

**Session:** Free Practice 2

**Fact:** Car #74 did not connect his data logger during the session

**Offence:** Breach of Article 502.1 and 504 of the GT World Challenge Europe powered by AWS 2026 Sporting Regulations

**Decision:** 2500€ Fine

**Reason:** Car #74 did not connect his data logger during the session. The team representative stated that the fact might happened after an intervention from the SRO TV crew. The TV crew representatives alleged that they did not touch any cable or part regarding the data logger. The Stewards agreed that, according to the regulations, the team is the sole responsible to guarantee that the data logger equipment is working problem at all times during the Competition. Noting this fact happened during Free Practice 2, the Stewards decide to impose a fine in this instance.

Competitors are reminded that they have the right to appeal certain decisions of the Stewards, in accordance with Article 15 of the FIA International Sporting Code, within the applicable time limits.

<b>Luis ROBY</b> Chair Steward	<b>Yves BACQUELAINE</b> Chair Steward	<b>Mathieu REMMERIE</b> Steward	<b>Chris GEFFROY</b> Steward	<b>Francesco MAFFEZZONI</b> Steward	<b>David FUENTES</b> Steward
-----------------------------------	------------------------------------------	------------------------------------	---------------------------------	----------------------------------------	---------------------------------

RECEIPT TO BE CONFIRMED ELECTRONICALLY BY THE COMPETITOR

Luis Roby Chair-Steward PT26-0509 25/06/2026, 19:14:54	David Fuentes Steward CD-1109-ESP/CAT 25/06/2026, 19:14:55	Mathieu Remmerie Steward 2613 25/06/2026, 19:14:55	Yves Bacquelaine Steward RACB 001 25/06/2026, 19:14:56	Francesco Steward ACI 229201 25/06/2026, 19:14:56	Chris Geffroy Steward FFSA 1031 25/06/2026, 19:14:56

The competitor is reminded that fines must be paid to:  
SRO MOTORSPORT FUND  
EURO BANK ACCOUNT  
SWIFT CODE RBOSGB2L  
IBAN GB05 RBOS 1610 7010 1487 81

