

POSTED at  
26/06/2026, 01:00:04

From The Technical Delegate  
To The Stewards of the Meeting

Report N° 07

Following technical checks carried out after Qualification Session 4, car #111 (CSA Racing) has been found to be in breach of BOP Decisions dated 19/06 regarding minimum splitter height: 45/42,3 mm : BOP is 50mm minimum,

Following technical checks carried out after Qualification Session 4, it has been reported by the official data technician that car #84 (Lionspeed GP) disconnected the datalogger before Qualification Sessions. We have no data from Qualification Sessions.

Series Technical Delegate

Date 25 juin 2026 Time: 23 :00

powered by **TotalEnergies**

